ECS/EMD Configuration Change Request

1. Originator Maryellen Corbett	2. Log Date: 5/18/04	3. CCR #: 04-0259	4. Rev: —	5. Tel: 301 925-0703	6. Rm #:	7. Org. COTS

8. CCR Title: Baseline Update May 2004 (#26)

9. Originator Signature/Date **Maryellen Corbett /s/ 5/17/04**	10. Class **II**	11. Type: **CCR**	12. Need Date: 5/29/2004
13. CCR Sponsor Signature/Date **Pamela Johnson /s/ 5/17/04**	14. Category of Change: Update ECS/EMD Baseline Doc		15. Priority: (If "Emergency" fill in Block 27). Routine

16. Documentation/Drawings Impacted *(Review and submit checklist):* See attached page	17. Schedule Impact:	18. CI(s) Affected:

19. Release Affected by this Change: EMD	20. Date due to Customer:	21. Estimated Cost: None - Under 100K

22. Source Reference: ☐NCR (attach)   ☐Action Item   ☐Tech Ref. ☐GSFC   ☐Other:

23. Problem: (use additional Sheets if necessary)
Some baseline inconsistencies have been identified. These may involve baseline updates and/or installation/removal of COTS products to resolve identified baseline inconsistencies.

24. Proposed Solution: (use additional sheets if necessary)
Provide baseline red-lines and/or ECOs to resolve identified discrepancies.   Attached sheet provides summary of baseline and system administration changes. These changes are also included in the ECO instructions for resolution of identified baseline discrepancies.

25. Alternate Solution: (use additional sheets if necessary)
Accept an inconsistent baseline and installations

26. Consequences if Change(s) are not approved: (use additional sheets if necessary)
Inconsistent baseline and installations

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF ☒PVC ☒VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL
           ☐EOC ☐ IDG Test Cell ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. SCDV CCB Chair (Sign/Date): **Byron V. Peters /s/ 5/20/04**	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
33. EDF CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS
34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS

ADDITIONAL SHEET

CCR #: 04-0259   **Rev: —**   **Originator:** Maryellen Corbett

Telephone: **Office:**

Title of Change: Baseline Update May 2004 (#26)

CM Documents:
920-TDP-002: PVC HW/SW Map
920-TDV-002: VATC HW/SW Map
910-TDA-003: COTS Version Baseline

Baseline Documentation updates ONLY:
1. Remove one of two identical AMASS entries from l0drg03. Only one entry needed.
2. Add SANergy 3.2.1.49 to the baseline of p0drg01. COTS product is currently correctly installed.
3. Add JRE 1.4.1 to the baseline of t1acg04. COTS product was baselined for this delivery in JRE 1.4.1 (SUN and SGI)
Maintenance Upgrade (# 914-TDA-255). COTS is currently correctly installed in this host.
4. Add JRE 1.4.1 to the baseline of t1aqg02. Product is currently correctly installed.
5. Remove JDOM 1.0beta8 from the baseline of t1dpg06. Product is not currently installed.
6. Change Remedy 5.1.2 ARS, Remedy MidTier 5.1.2 and Remedy Patch (Mid Tier) paths to /usr/ecs/OPS/COTS/remedy512.
7. Remove RDAC fron the baseline of t1mss06. Product should not be baselined and is not currently installed.
8. Remove NTP 4.1.0 as a separate baseline entry for PVC and VATC hosts. The original delivery of NTP was accomplished via
separate PSR. Sun NTP delivery has been included with OS maintenance for some time. With the delivery of IRIX 6.5.2, NTP will
be included with IRIX maintenance upgrades also.

Infrastructure Baseline Updates/ECOs:
1. Install WU-FTP 2.6.2 as identified in WU-FTPD Version 2.6.2 Update for Sun and SGI (document # 914-TDA-230)on t1acg04.
COTS product is baselined and is currently NOT installed.